Sepcifications:

Measuring range[] ± 10 kPa Accuracy: $\pm 0.3\%$ FSO(25°C) Repeatability: ± 0.2 (Maximum[]/[]0.5 FSO) Linearity/hysteresis: ± 0.29 FSO Response:Typical 0.5 s Low battery indication: Yes Up overload indication: Err1 Down overload indication: Err2 Operating temperature: $0 \sim 50$ °C Storage temperature: $-10 \sim 60$ °C Power supply: 1.5V AAA battery*4 USB communication: Yes